


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-271	Smoke	9/2/2009	ADS/TM	S11MM1018MH	Dry	Yes	1,138.87



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-271	Smoke	9/2/2009	ADS/TM	S11MM1018MH	Dry	Yes	1,138.87

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11MM1010G1	S11MM1010MH	S11MM1023MH	200.48	8
S11MM1018G1	S11MM1018MH	S11MM1023MH	128.798	8
S11MM1023G1	S11MM1023MH	S11MM1015MH	128.675	8
S11MM1028G1	S11MM1028MH	S11MM1015MH	206.258	8
S11OO1018G1	S11OO1018MH	S11MM1018MH	169.51	8
S11OO1024G1	S11OO1024MH	S11OO1018MH	305.146	8


Observations & Photos

Obs_ID S1028-271-OB01
Address 3114 Woodland Ave
Status Private
Source Cleanout

Location Yard - front

Nearest MH S11MM1018MH

Comments Smoke from cleanout in front yard. 3114 Woodland Ave.



Picture \S1028-271-OB01-P01.jpg

Comments Front of house, 3114 Woodland Ave.

Obs_ID S1028-271-OB02
Address 3108 Woodland Ave
Status Private
Source Cleanout

Location Yard - front

Nearest MH S11OO1018MH

Comments Smoke from cleanout in front yard. 3108 Woodland Ave.



Picture \S1028-271-OB02-P01.jpg

Comments Front of house, 3108 Woodland Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-271	Smoke	9/2/2009	ADS/TM	S11MM1018MH	Dry	Yes	1,138.87

Obs_ID S1028-271-OB03

Address 3000 Woodland Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001024MH

Comments Smoke from cleanout in front yard. 3000 Woodland Ave.



Picture \S1028-271-OB03-P01.jpg

Comments Front of house, 3000 Woodland Ave.

Obs_ID S1028-271-OB05

Address 3116 Woodland Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11MM1018MH

Comments Smoke from cleanout in front yard. 3116 Woodland Ave.



Picture \S1028-271-OB05-P01.jpg

Comments Front of house, 3116 Woodland Ave.

Obs_ID S1028-271-OB04

Address 3002 Woodland Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11001024MH

Comments Smoke from cleanout in front yard. 3002 Woodland Ave.



Picture \S1028-271-OB04-P01.jpg

Comments Front of house, 3002 Woodland Ave.

Obs_ID S1028-271-OB06

Address 4805 Park Heights Ave

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1023MH

Comments Smoke from service lateral in back yard. 4805 Park Heights Ave.



Picture \S1028-271-OB06-P01.jpg

Comments Back of house, 4805 Park Heights Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-271	Smoke	9/2/2009	ADS/TM	S11MM1018MH	Dry	Yes	1,138.87

Obs_ID S1028-271-OB07

Address 4809 Park Heights Ave

Status Private

Source Cleanout

Location Paved concrete

Nearest MH S11MM1023MH

Comments Smoke from cleanout in paved concrete behind house. 4809 Park Heights Ave.



Picture \S1028-271-OB07-P01.jpg

Comments Back of house, 4809 Park Heights Ave.

Obs_ID S1028-271-OB09

Address 3129 Woodland Ave

Status Public

Source Sanitary Manhole

Location Paved asphalt

Nearest MH S11MM1023MH

Comments Smoke from sanitary manhole S11MM1023MH (vented lid) in paved asphalt in front of 3129 Woodland Ave.



Picture \S1028-271-OB09-P01.jpg

Comments Front of house, 3129 Woodland Ave.

Obs_ID S1028-271-OB08

Address 4817 Park Heights Ave


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1010MH

Comments Smoke from service lateral under paved concrete behind house. 4817 Park Heights Ave.



Picture \S1028-271-OB08-P01.jpg

Comments Back of house, 4817 Park Heights Ave.

Obs_ID S1028-271-OB10

Address 4755 Park Heights Ave


Status Public

Source Catch Basin

Location Curb

Nearest MH S11MM1023MH

Comments Smoke from catch basin along curb in front of 4755 Park Heights Ave.



Picture \S1028-271-OB10-P01.jpg

Comments Park Heights Ave. & Woodland Ave. looking southeast

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-271	Smoke	9/2/2009	ADS/TM	S11MM1018MH	Dry	Yes	1,138.87

Obs_ID S1028-271-OB11

Address 3129 Woodland Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1015MH

Comments Smoke from service lateral in back yard. 3129 Woodland Ave.



Picture \S1028-271-OB11-P01.jpg

Comments Back of house, 3129 Woodland Ave.

